




www.mazdarotaryparts.com

The Old Rectory Business Centre
Springhead Road, Northfleet, Kent
DA11 8HN t: + 44 [0] 1474 361800

FD-0718

FD RX7: CLUTCH RELEASE ARM INFORMATION

If you are fitting a new Clutch assembly you may want to consider renewing the Clutch release arm. This is an increasingly common point of failure on the FD RX-7 as they get older. The small expense (in addition to the cost of the clutch) is well worth it as failure can come with little or no warning. As is often the case, replacement of major components can expose pre-existing weaknesses in others. The pictures show where both types of failure occur.



Please call for up-to-the-minute pricing on this part